

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: _____

It is certified that the existing building Principal P.M. Shri. GMSSSB, Nagrota Bagwan (name of the building or premises) at Nagrota Bagwan Distt. Kangra (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Science Block	Arts Block	old Block	—	—	—
	3 Story	3 story	2 Story	—	—	—

The building is owned/occupied by Education Department, P.M. Shri. GMSSSB, Nagrota Bagwan (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of H.P. P.W.D. Nagrota Bagwan (Name of Department/ Govt.) on 6/10/2025 (date of inspection) in the presence of Junior Engineers, H.P. P.W.D. (Shri. Harish Kumar) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from _____ for a period of one year (2025-2026) years in accordance with rule and subject to compliance of the specific conditions as appended:

1. _____
2. _____
3. _____
4. _____

Issued on _____ at _____ by _____

* Strike out whichever is not applicable, in case of block is more than six use separate sheet for detail:

Signature with Seal: _____
 Name: Executive Engineer
 H.P. P.W.D. Division Tanda
 Designation: Nagrota Bagwan
 Name & Address of Department/ Office: _____

Assistant Engineer
 Nagrota Sub Division
 H.P. P.W.D. Nagrota Bagwan
 Distt. Kangra (HP)

Self Attested
 Principal
 PM Shri GMSSSB (B)
 Nagrota Bagwan